

GS1 DataBar Readiness Survey							
Note: For Scanner type field put in #: For region field: place "X" where sold							
GS1 DataBar Ready Scanners							
Company Name	Model	Scanner Type	Region				
		1. Omni Hi speed checkout, 2. Presentation,3. HH Imager, or 4. HH Linear 5. Fixed Mount Linear 6. Fixed Mount Omni 7. Fixed Mount Imager	US/Canada	Europe	Asia Pacific	South & Latin America	Middle East & Africa
Motorola	MS-3223	6	X	X	X	X	X
Motorola	LS 2208	4	X	X	X	X	X
Motorola	LS 1203	4	X	X	X	X	X
Motorola	DS670X	3	X	X	X	X	X
Motorola	LS920X	2	X	X	X	X	X
Motorola	LS7707	1	X	X	X	X	X
Motorola	LS7808	1	X	X	X	X	X
Motorola	M200X	2	X	X	X	X	X
Motorola	LS3008	4	X	X	X	X	X
Motorola	LS34XX	4	X	X	X	X	X
Motorola	LS35XX	4	X	X	X	X	X
Motorola	DS34XX	3	X	X	X	X	X
Motorola	LS42XX	4	X	X	X	X	X
Motorola	MS-32xx	6	X	X	X	X	X
Motorola	MS-22xx	5	X	X	X	X	X
Motorola	MS-12xx	5	X	X	X	X	X
Motorola	MS-954	5	X	X	X	X	X
Motorola	MS-44xx	7	X	X	X	X	X
Motorola	SE-95x	5	X	X	X	X	X
Motorola	SE-12xx	5	X	X	X	X	X
Motorola	SE-22xx	5	X	X	X	X	X
Motorola	SE-32xx	6	X	X	X	X	X
Motorola	SE-44xx	6	X	X	X	X	X

Motorola	SE-45xx	7	X	X	X	X	X
Motorola	SE-15xx	5	X	X	X	X	X
Motorola	SE-6700	6	X	X	X	X	X
These are scan engines not finished product							
<b>Scanners which can not be upgraded to GS1 DataBar (RSS)</b>							
P370							
P470							
P360							
P460							
<b>Scanners requiring GS1 DataBar Upgrade</b>							
		<b>Scanner Type</b>	<b>Region</b>				
Company Name	Model	1. Omni Hi speed checkout, 2. Presentation,3. HH Imager, or 4. HH Linear	US/Canada	Europe	Asia Pacific	South & Latin America	Middle East & Africa
Not Applicable							